

Weighing and Radio Technology










WT-1 or WT 2 are easy to mount. Load pins provide a higher accuracy. Overload relay has two cut-off outputs. Display with linearization function.





Mechanical Overload Switch.

Customized Weighing Solutions and Radio Remote Controls for